



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
03/24/2006

Supervisor 1007

Mine Name: Leamington Cement Plant
Operator Name: Ash Grove Cement Company
P.O. Box 51
Nephi, Utah 84648
Inspector(s): Tom Munson
Other(s): Jeff Peterson and Josh Nelson
Mine Status: Active

Permit number: M230004
Inspection Date: 03/23/06
Time: 10 AM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: To perform an Annual inspection, focusing on sediment control.

Directions to Site: The site sits west of Nephi on Route 132 East of the town of Leamington.

Inspection Summary:

I visited two sediment ponds found within the mine site. One was dry and the other had a small amount of water in it. Neither pond has been pumped out or needed to be cleaned due the lack of runoff and sediment leaving the site.

The majority of the site was inactive except for the Hank Allen Quarry on the east end of the property where the recently blasted material was being hauled to the crusher.

We viewed various stockpiled materials on our inspection and talked of future expansion plans, regarding the Hank Allen site.

Conclusions and Recommendations:

Earth Fax engineering will be sending us expansion plans as an amendment to the permit shortly.

Inspector's Signature Thomas Munson

Date: 3/24/2005

tm:pb

cc: Operator


Attachment: Photos

P:\GROUPS\MINERALS\WP\M023-Juab\M0230004-Leamington\final\insp03232006.doc




03.23.2006 12:51

LEAMINGTON MO230004



SEDIMENT POOL
LEAMINGTON
M0230004



LEAMINGTON
M0230004

HANK ALLEN
QUARRY

03.23.2006 13:30

LEAMINGTON MO230004